

SEAMARK™

Limited Warranty

SeaMark-carries the Sunbrella-fabric limited five-year warranty.

This warranty covers the face fabric becoming unserviceable because of loss of color or strength from normal exposure to conditions including sunlight, mildew, rot and atmospheric chemicals. It does not cover labor and installation supplied by the dealer.

Care and Cleaning

Although the fabric does not promote mildew growth by itself, mildew may develop on dirt and other foreign substances that are not removed. This is especially true in warm, humid, dark environments. A program of keeping the fabric clean through regular washings, BEFORE it gets dirty, will enhance the life and beauty of the acrylic and make successive cleaning easier.

Haartz Corporation recommends using Bimini Topp- Marine Cleaner and Bimini Topp- Marine Protectant. (Available from Wolfsteins Pro-Series. www.wolfsteins.com.)

Hand washing in shade or partial shade, not direct sunlight, is best. DO NOT USE DETERGENT. Bird and tree droppings, as well as other loose particle soilage, should be removed immediately. Vacuum with a brush attachment and rinse thoroughly with water to remove loose particle soils. This will also prevent the soils from being redeposited during the cleaning process. Once the fabric has been rinsed thoroughly, spray Bimini Topp- Marine Cleaner evenly over the entire surface while still wet. Allow the cleaner to soak for 10 to 20 minutes and then scrub lightly with a soft nylon brush or terry cloth rag. Rinse thoroughly, preferably until no remaining soap foam is observed. Additional cleanings may be required. It is best to determine the need for additional cleanings after the fabric has dried completely.

Once dry, cleaning must be followed by re-water repelling with Bimini Topp- Marine Protectant. (This product does not contain CFCs and therefore, is not harmful to the environment.) Failure to apply will result in rapid resoiling of the unprotected fabric.

Washing with soap (i.e. Ivory or Lux) and warm water is a safe alternative to Bimini Topp™ Marine Cleaner, but not as effective.

For more stubborn cases, mix a solution of no more than 1/2 cup (4 oz.) bleach and 1/4 cup (2 oz.) Bimini Topp- Marine Cleaner per gallon of water, soak for approximately 20 minutes and scrub lightly as indicated above. (Excessive soaking with the bleach solution can deteriorate seam threads.) Rinse thoroughly to prevent streaking on painted and chrome surfaces. Several cleanings may be necessary. Once again, Bimini Topp- Marine Protectant water repellent must be applied to the fully dried fabric.